

FIG-1




FIG. 3




FIG-3




FIG- 4

FIG. 5A




FIG. 5B







FIG-6












FIG-9

FIG-10




FIG-11A




FIG-11B




FIG-11C





FIG-11 D



220 →

FIG 12 C




FIG-12 B





FIG-12 A

FIG- 12E




FIG- 12D




FIG. 13 is a perspective view of the machine of FIG. 12, showing the machine in a second position, with the machine body 20 tilted to a second angle, and the machine body 20 tilted to a second angle, and the machine body 20 tilted to a second angle.




FIG-13

FIG-14 B





FIG-14A




FIG-14C






FIG-10

